



International Maritime Pilots' Association (IMPA)
HQS Wellington, Temple Stairs, Victoria Embankment, London WC2R 2PN
Telephone: +44 20 7240 3973 Fax: +44 20 7240 3518
Email: office@impahq.org
Website: www.impahq.org



SAFETY CAMPAIGN 2010

CONTENTS

- 2 IMPA Officers
IMPA Secretariat
- 3 Foreword
- 4 Participating
Countries
- 5 Vessel Type
- 6 Compliance By
Means of Transfer
- 7-9 Non-Compliance By
Type of Defect
- 10 Required Boarding
Arrangements for
Pilot
- 11 Our Mission

IMPA OFFICERS

President

Captain Michael Watson – *USA*

Senior Vice-President

Captain Otavio Fragoso – *Brazil*

Vice-Presidents

Captain Steve Pelecanos – *Australia*

Captain Cahit Istikbal – *Turkey*

Captain Simon Pelletier – *Canada*

Captain Stig Thomsen – *Denmark*

Captain Frédéric Moncany – *France*

Adviser Representatives

Captain José Faraldo – *Cuba*

Captain Koichi Uehara – *Japan*

Captain José Burgos – *Panama*

Captain Don Cockrill – *UK*

Captain Chris Lefèvre – *Belgium*

Captain Oumar Drame – *Senegal*

IMPA SECRETARIAT

Secretary General

Mr Nick Cutmore

Executive Secretary

Mrs Caron James

Executive Assistant

Miss Marie-Claire Jenkins

HQS Wellington

Temple Stairs

Victoria Embankment

London WC2R 2PN

Tel: +44 20 7240 3973

Fax: +44 20 7240 3518

Email: office@impahq.org

Website: www.impahq.org

This campaign was run during one week at the end of September 2010 in response to a request from IMO at NAV 55 for an indication of whether standards of pilot boarding arrangements were improving or declining. It involved the membership of IMPA together with our colleagues in the European Maritime Pilots' Association and its purpose is to provide a snapshot of the standards of boarding equipment and facilities offered to pilots during embarkation and disembarkation from vessels. Pilot transfer at sea remains a treacherous part of the vital task needed in maintaining a continuous pilotage service that provides the essential knowledge and skills that today's ships need so very much. It is 3 years since the last Safety Campaign whose report was notified to IMO, which in turn followed a peak in fatalities to pilots and launch crews in 2006. The losses of 2006 led to IMPA putting forward to IMO in conjunction with the United States and Brazil, a paper seeking modification and improvements to ladder arrangements.

32 national pilotage organizations contributed to this study by making a total of 2,251 entries onto the database. This is the first time an electronic reporting system has been used. These total figures can be

considered representative and indicative enough of what is happening globally and enables us to draw broad conclusions. As will be noted from the detailed breakdowns the defect level was 13.54% which though still too high, does confirm the downwards trend noted since 2002 (22%) and in 2007 (17%).

It would be complacent to believe that pilots were not to a degree involved in this state of affairs, even just for their tacit acquiescence. Pilots have a 'can-do' mentality that can lead them to use less than satisfactory boarding equipment, sometimes to their great cost. Pilots are also notoriously reluctant to report defects to Port State Control, which is a legacy for many of their previous life as Masters. IMPA will continue to press its members to take greater care of themselves and exercise greater diligence over the equipment they use.

One of the most significant benefits of the revisions, which we hope will be adopted by IMO and included in a revised SOLAS Chapter V Regulation 23, will be the requirement for boarding arrangements to be inspected as part of the Ship's safety equipment. This is a significant step forward.




Ladders can injure vessel crews too! An A.B. on this vessel fell into the North Sea in October 2010 when this accommodation ladder platform collapsed under him. The man, wearing just a boiler suit with no life jacket or PPE, was retrieved by the Pilot Cutter. He was treated by Paramedics and returned to his ship, unscathed. The cause of the accident, according to the Master, was a failed weld, on a repair made a few weeks earlier.



PARTICIPATING COUNTRIES

The charts below show the participating countries, i.e. the member countries where pilots took part in the survey. It is not indicative of the flag of the vessels surveyed. In addition it shows the total returns for each participating country and the total non-compliance as a percentage of returns from that country.

| COUNTRY | TOTAL RETURNS | COMPLIANT | NON COMPLIANT | NON COMPLIANT AS % | COUNTRY | TOTAL RETURNS | COMPLIANT | NON COMPLIANT | NON COMPLIANT AS % |
|-----------|---------------|-----------|---------------|--------------------|--------------|---------------|-------------|---------------|--------------------|
| Argentina | 141 | 118 | 23 | 16.31 | Japan | 599 | 585 | 14 | 2.34 |
| Australia | 37 | 23 | 14 | 37.84 | Korea | 1 | 1 | 0 | 0.00 |
| Belgium | 9 | 8 | 1 | 11.11 | Latvia | 1 | 1 | 0 | 0.00 |
| Brazil | 88 | 76 | 12 | 13.64 | Morocco | 38 | 27 | 11 | 28.95 |
| Bulgaria | 10 | 7 | 3 | 30.00 | Netherlands | 23 | 15 | 8 | 34.78 |
| Canada | 26 | 23 | 3 | 11.54 | Norway | 57 | 44 | 13 | 22.81 |
| Chile | 36 | 29 | 7 | 19.44 | Panama | 19 | 16 | 3 | 15.79 |
| Cyprus | 2 | 2 | 0 | 0.00 | Poland | 12 | 12 | 0 | 0.00 |
| Denmark | 13 | 12 | 1 | 7.69 | Portugal | 55 | 47 | 8 | 14.55 |
| Finland | 2 | 2 | 0 | 0.00 | Senegal | 53 | 51 | 2 | 3.77 |
| France | 440 | 354 | 86 | 19.55 | Slovenia | 75 | 66 | 9 | 12.00 |
| Germany | 17 | 15 | 2 | 11.76 | Spain | 23 | 18 | 5 | 21.74 |
| Greece | 1 | 1 | 0 | 0.00 | Turkey | 48 | 36 | 12 | 25.00 |
| Guatemala | 41 | 37 | 4 | 9.76 | UK | 212 | 168 | 44 | 20.75 |
| Ireland | 21 | 17 | 4 | 19.05 | Uruguay | 5 | 5 | 0 | 0.00 |
| Italy | 107 | 92 | 15 | 14.02 | USA | 39 | 38 | 1 | 2.56 |
| | | | | | Total | 2251 | 1946 | 305 | 13.55 |




VESSEL TYPE

The following chart shows a break down of all returns by vessel type. Both the number and the percentage of noncompliant vessels by type are shown.



Is this a gunport or a door?

| VESSEL TYPE | TOTAL NUMBER OF VESSELS | COMPLIANT | NON COMPLIANT | NON COMPLIANT AS % |
|------------------|-------------------------|-----------|---------------|--------------------|
| General Cargo | 330 | 254 | 76 | 23.03 |
| Oil Tanker | 303 | 269 | 34 | 11.22 |
| Ro/Ro | 131 | 110 | 21 | 16.03 |
| Passenger | 152 | 133 | 19 | 12.50 |
| Container | 550 | 486 | 64 | 11.64 |
| Gas Tanker | 84 | 76 | 8 | 9.52 |
| Reefer | 28 | 28 | 0 | 0.00 |
| Fishing | 15 | 11 | 4 | 26.67 |
| Bulkcarrier | 287 | 258 | 29 | 10.10 |
| Chemical Tanker | 103 | 87 | 16 | 15.53 |
| Car Carrier | 139 | 138 | 1 | 0.72 |
| Other (eg. Navy) | 165 | 128 | 37 | 22.42 |






COMPLIANCE BY MEANS OF TRANSFER

The following chart shows a break down of all returns by vessel type. Both the number and the percentage of noncompliant vessels by type are shown.

| MEANS OF TRANSFER | TOTAL NUMBER | COMPLIANT | NON COMPLIANT | NON COMPLIANT AS % |
|-------------------|--------------|-----------|---------------|--------------------|
| Pilot Ladder | 1583 | 1378 | 205 | 12.95 |
| Combination | 358 | 312 | 46 | 12.85 |
| S/D+Pilot Ladder | 180 | 152 | 28 | 15.56 |
| Pilot Hoist | 8 | 8 | 0 | 0.00 |
| Gangway | 29 | 27 | 2 | 6.90 |
| Side Door | 50 | 35 | 15 | 30.00 |
| Deck to Deck | 68 | 49 | 19 | 27.94 |
| Helicopter | 18 | 17 | 1 | 5.56 |




NON-COMPLIANCE BY TYPE OF DEFECT

| | |
|--------------------------------------|-------|
| TOTAL NUMBER OF NON-COMPLIANT SHIPS | 305 |
| No. of defects reported to Authority | 38 |
| % of non-compliant ships reported | 12.46 |

Number of defects reported to Authority (Blue)

Number of defects not reported to Authority (Red)



| NON-COMPLIANT BY TYPE OF DEFECT | TOTAL | AS % |
|---------------------------------|-------|-------|
| Pilot Ladder | 166 | 47.56 |
| Bulwark | 43 | 12.32 |
| Side Door | 12 | 3.44 |
| Combination | 27 | 7.74 |
| Safety Equipment | 101 | 28.94 |




Pilot Ladder (Blue)

Bulwark (Red)

Side Door (Green)

Combination (Purple)




Safety Equipment (Light Blue)





NON-COMPLIANCE
BY TYPE OF DEFECT



| DEFECTS OF PILOT LADDER | TOTAL | AS % |
|------------------------------------|-------|-------|
| Not against ship's hull | 39 | 17.73 |
| Steps not of suitable material | 11 | 5.00 |
| Badly placed retrieval line | 20 | 9.09 |
| Steps broken | 13 | 5.91 |
| Steps not equally spaced | 24 | 10.91 |
| Pilot Ladder more than 9 metres | 7 | 3.18 |
| Steps dirty / Slippery | 33 | 15.00 |
| Sideropes not of suitable material | 16 | 7.27 |
| Pilot Ladder too far forward / Aft | 15 | 6.82 |
| Steps painted | 9 | 4.09 |
| Sideropes joined below bottom step | 21 | 9.55 |
| Not bulwark ladder | 12 | 5.45 |




Ladder offered to pilot in Liverpool by the aptly-named vessel 'Great Chance'

NON-COMPLIANCE
BY TYPE OF DEFECT

| COMBINATION DEFECTS | TOTAL | AS % |
|---|-------|-------|
| Accommodation Ladder not leading aft | 0 | 0 |
| Lower platform stanchions / rail incorrect | 8 | 19.51 |
| Accommodation Ladder too steep (>45 degrees) | 2 | 4.88 |
| Pilot Ladder not attached to Accommodation Ladder | 22 | 53.66 |
| Lower platform not horizontal | 7 | 17.07 |
| No 9 metres mark on ship's side | 2 | 4.88 |




| SAFETY EQUIPMENT DEFECTS | TOTAL | AS % |
|---|-------|-------|
| Inadequate lighting at night | 14 | 6.90 |
| No standby ladder rigged for immediate use | 30 | 14.78 |
| No lifebuoy with self-igniting light | 71 | 34.98 |
| No VHS communication with the bridge | 29 | 14.29 |
| No heaving line | 45 | 22.17 |
| No Responsible officer or deckman in attendance | 14 | 6.90 |



REQUIRED BOARDING ARRANGEMENTS FOR PILOT

In accordance with I.M.O. requirements and I.M.P.A. recommendations
INTERNATIONAL MARITIME PILOTS' ASSOCIATION
 H.Q.S "Wellington", Temple Stairs, Victoria Embankment, London WC2R 2PN Tel: +44 20 7240 3973 Fax: +44 20 7240 3518



OUR MISSION

IMPA represents the international community of pilots. We use the resources of our membership to promote effective safety outcomes in pilotage as an essential public service.

BELIEFS

- 1 The public interest is best served by a fully regulated and cohesive pilotage service free of commercial pressure.
- 2 There is no substitute for the presence of a qualified pilot on the bridge.
- 3 IMO is the prime authority in matters concerning safety of international shipping.
- 4 All states should adopt a responsible approach based on proven safety strategies in establishing their own regulations, standards and procedures with respect to pilotage.
- 5 Existing and emerging information technologies are capable of enhancing on-board decision making by the maritime pilot.

